

# FLUID SECTION REPAIR KIT F/MOD. 307

Product group: **427**      Product number: **607832**  
Fluid section repair kit (diaphragms/balls/seats) for mod. 307, polypropylene



## Product information

## Specification

General

Invent Hazard Material (IMO/IU) classification	NA
--	----

## Documents

[SDoC and MD for IHM](#)

## Related products

Is accessory to

**604918**  
DOUBLE DIAPHRAGM PUMP 307 POLY

Is frequently bought together with

**191874**  
20 UPMP LUG 1/4" MALE BSP.T

**607833**  
AIR VALVE KIT

**191684**  
30 USH SOCKET 3/8" HOSE

**552497**  
ELECTRODE HOLDER TWISTY 200AMP

**513051**  
ELECTRODE HOLDER TWISTY 400AMP