

FLUID SECTION REPAIR KIT F/MOD. 307

Product group: **427** Product number: **607832**

Fluid section repair kit (diaphragms/balls/seats) for mod. 307, polypropylene



Product information

Specification

General

Invent Hazard Material (IMO/EU) classification	NA
--	----

Documents

[SDoC and MD for IHM](#)

Related products

Is accessory to

604918
DOUBLE DIAPHRAGM PUMP 307 POLY

Is frequently bought together with

191874
20 UPMP LUG 1/4" MALE BSP.T

607833
AIR VALVE KIT

191684
30 USH SOCKET 3/8" HOSE

552497
ELECTRODE HOLDER TWISTY 200AMP

513051
ELECTRODE HOLDER TWISTY 400AMP

This page is printed from

<https://www.wilhelmsen.com/product-catalogue/products/pumps/accessories--spares/double-diaphragm-accessories--spares/fluid-section-repair-kit-f-mod.-307>