

Product group: **604**      Product number: **636688**

Removing contaminants such as acids and moisture in refrigeration system can be done by inline driers, which should be replaced annually. When a burnout in the semi-hermetic or hermetic compressor has occurred it should be replaced immediately.

Product information

This product supersedes product no: **548347**

Features

- 2 driers per pack
- Ready to use
- Connection 1/2" SAE flare
- Overall length 180 mm and 65 mm diameter

Benefits

- Removes moisture and acid

Specification

General

Invent Hazard Material (IMO/IEU) classification	NA
---	----

Dimensions/Weight

Connection [Size/ Type]	1/2 FLARE (2-PACK)
Diameter [mm]	
Length [mm]	

Documents

[Filter-drier-with-Drawing](#)

[SDoC and MD for IHM](#)

Related products

Is frequently bought together with

- 607826**  
AQUATUFF 25 LTR
- 571687**  
DISCLEAN 25 LTR
- 905034**  
OXYGEN O-40 FILLING
- 905026**  
ACETYLENE A-40 FILLING
- 548255**  
LIQUID LINE DRIER CORE (MODEL 48-DC)