

Product group: 427 Product number: 607835

Fluid section repair kit (diaphragms/balls/seats) for mod. 2150, stainless steel



Product information

This product supersedes product no: 783832

Specification

General

Invent Hazard Material (IMO/IU) classification	NA
--	----

Documents

[SDoC and MD for IHM](#)

Related products

Is accessory to

604926
DOUBLE DIAPHRAGM PUMP 2150 ALU

Is frequently bought together with

191890
40 UPMP LUG 1/2" MALE BSP.T

607817
SUCTION HOSE 2 IN 5 MTR

604926
DOUBLE DIAPHRAGM PUMP 2150 ALU

191692
40 USH SOCKET 1/2" HOSE

699173
GPO-302N 3.2X350MM 190 PCS 5.4 KG

This page is printed from:

<https://www.wilhelmsen.com/product-catalogue/products/pumps/accessories--spares/double-diaphragm-accessories--spares/fluid-kit-fmod-2150-alum/>