

## Product group: 604 Product number: 636621

Removing contaminants such as acids and moisture in refrigeration systems can be done by inline driers, which should be replaced annually. When a burnout in the semi-hermetic or hermetic compressor has occurred it should be replaced immediately.

## **Product information**

This product supersedes product no: 548289

## Features

- 2 driers per pack
- Ready to useConnection 3/8" SAE flare
- Overall length 130 mm and 50 mm diameter

## Benefits

• Removes moisture and acid

### **Specification**

#### General

Invent Hazard Material (IMO/EU) classification

NA

## Dimensions/Weight

Connection [Size/ Type]	3/8 FLARE (2-PACK)
Diameter [mm]	50 C
Length [mm]	130 B

# **Documents**

Filter-drier-with-Drawing

SDoC and MD for IHM

# **Related products**

Is frequently bought together with 632406 TBN REAGENT PACK 522557 TUBE CUTTER UPT-274-FC 548255 LIQUID LINE DRIER CORE (MODEL 48-DC) 636431 1/4-3/8 COLLECTION OF FITTINGS 633065 WELDING CURTAIN W/HOOKS

#### This page is printed from:

https://www.wilhelmsen.com/product-catalogue/products/refrigeration-equipment/system-equipment--spares/filter-drier-ufd-053f-2pcs/