

Product group: **604** Product number: **636670**

Removing contaminants such as acids and moisture in refrigeration system can be done by inline driers, which should be replaced annually. When a burnout in the semi-hermetic or hermetic compressor has occurred it should be replaced immediately.

Product information

This product supersedes product no: **548339**

Features

- 2 driers per pack
- Ready to use
- Connection 3/8" SAE flare
- Overall length 170 mm and 65 mm diameter

Benefits

- Removes moisture and acid

Specification

General

Invent Hazard Material (IMO/EU) classification	NA
--	----

Dimensions/Weight

Connection [Size/ Type]	3/8 FLARE (2-PACK)
Diameter [mm]	
Length [mm]	

Documents

[Filter-drier-with-Drawing](#)

[SDoC and MD for IHM](#)

Related products

Is frequently bought together with

- 632406**
TBN REAGENT PACK
- 511006**
ELECTRODE HOLDER UNIKING 600AMP
- 175802**
WELDING CABLE & CONNECTOR 50 MM2 50M
- 620034**
GAS HOSE 9.0MM (3/8INCH) RED,50 MTR COIL
- 620038**
GAS HOSE 9.0MM (3/8INCH) BLUE,50 MTR COIL