

Product group: 604 Product number: 636688

Removing contaminants such as acids and moisture in refrigeration system can be done by inline driers, which should be replaced annually. When a burnout in the semi-hermetic or hermetic compressor has occurred it should be replaced immediately.

Product information

This product supersedes product no: 548347

Features

- 2 driers per pack
- Ready to use
- Connection 1/2" SAE flare
- Overall length 180 mm and 65 mm diameter

Benefits

- Removes moisture and acid

Specification

General

Invent Hazard Material (IMO/IU) classification	NA
--	----

Dimensions/Weight

Connection [Size/ Type]	1/2 FLARE (2-PACK)
Diameter [mm]	
Length [mm]	

Documents

[Filter-drier-with-Drawing](#)

[SDoC and MD for IHM](#)

Related products

Is frequently bought together with

- 905026
ACETYLENE A-40 FILLING
- 905034
OXYGEN O-40 FILLING
- 571687
DISCLEAN 25 LTR
- 607826
AQUATUFF 25 LTR
- 548255
LIQUID LINE DRIER CORE (MODEL 48-DC)

This page is printed from:

<https://www.wilhelmsen.com/product-catalogue/products/refrigeration-equipment/system-equipment--spares/filter-drier-ufd-164f-12-fl.-2pc/>