



PROTECTION GLASS. 10PCS

Product group: **196** Product number: **633214**

Protection glass is absolutely necessary to guard the welder against the danger of burns, ultra-violet rays and bits of welding slag in the eye.



Product information

This product supersedes product no: **175711**

The glasses have dimensions 60 x110 mm and are manufactured in accordance with DIN standard and are CE approved. When ordering face shields, filter shade glass of correct shade should be ordered in addition to the filter shade 11 glasses which is included. The filter glasses are supplied in sets consisting of 5 safety glasses, 5 protection glasses and 5 filter shade glasses.

Features

- Made from a lightweight, robust plastic material which is unaffected by heat, cold or moisture
- Both glasses and shields conform to relevant EN standards

Specification

General

Invent Hazard Material (IMO/EU) classification	NA
--	----

Variants

Product name	Product number
<u>PROTECTION GLASS. 10PCS</u>	633214 (supersedes 175711)
<u>SAFETY GLASS. 10PCS</u>	633222 (supersedes 511964)
<u>SHADE 10 GLASS. 5SET</u>	633255 (supersedes 175679)
<u>SHADE 11 GLASS. 5SET</u>	633263 (supersedes 175687)
<u>SHADE 12 GLASS. 5 SET</u>	633271 (supersedes 175695)
<u>SHADE 13 GLASS. 5 SET</u>	633289 (supersedes 175703)
<u>SHADE 8 GLASS. 5SET</u>	633230 (supersedes 175653)
<u>SHADE 9 GLASS. 5SET</u>	633248 (supersedes 175661)

Approvals

CE

Directions for use

A. Safety glass (polycarbonate)
The glass is used in shields with a flip-up front frame and should be placed nearest to the eyes to protect against slag or other articles while chipping/ grinding when the flip up front is open.

B. Filter shade glass

Filters out harmful infra-red and ultra-violet rays from the welding arc, and reduces visible light to a level which is sufficient to see the welding process without straining the welder's eyes. Filter Shade Glass should be selected based on welding process and amperage. The glasses are marked Protane Shade SO 1 DIN 0196 CE

C. Protection glass

The glass is placed in front of the filter shade glass to protect against spatter. The protection glass should be replaced at regular intervals.

Related products

Is accessory to

619114 SAFETY HELM W/FACE SH.

709485 FLIPVISION WELDING FACE SHIELD

619098 FACE SHIELD W/HANDLE

Is frequently bought together with

633222 SAFETY GLASS. 10PCS

632786 WELDERS GLOVES. 6 PAIRS

175273 WELD.GOGGLES W/LIFT-FRONT

699173 GPO-302N 3.2X350MM 190 PCS 5.4 KG

633263 SHADE 11 GLASS. 5SET

This page is printed from:

<https://www.wilhelmsen.com/product-catalogue/products/welding/arc-welding-equipment/welders-protection/protection-glass.-10pcs/>