


Product group: 196 Product number: 633263

Filter glasses for arc welding

Product information

This product supersedes product no: 175687



Specification

General

Invent Hazard Material (IMO/EJ) classification

Approvals

CE

Documents

SDoC and MD for IHM

Directions for use

A Safety glass (polycarbonate)

The glass is used in shields with a flip-up front frame and should be placed nearest to the eyes to protect against slag or other articles while chipping/ grinding when the flip up front is open.

B. Filter shade glass

Filters out harmful infra-red and ultra-violet rays from the welding arc, and reduces visible light to a level which is sufficient to see the welding process without straining the welder's eyes. Filter Shade Glass should be selected based on welding process and amperage. The glasses are marked Protane Shade SO 1 DIN 0196 CE

C. Protection glass

The glass is placed in front of the filter shade glass to protect gainst spatter. The protection glass should be replaced at regular intervals.

Related products

Is accessory to

709485

FLIPVISION WELDING FACE SHIELD

619098

FACE SHIELD W/HANDLE

619114

SAFETY HELMW/FACE SH.

Is frequently bought together with

905034

OXYGEN O-40 FILLING

699165

GPO-302N 2.5X350MM295 PCS 5,2KG

699173

GPO-302N 3.2X350MM 190 PCS 5.4 KG

632786

WELDERS GLOVES. 6 PAIRS

633214

PROTECTION GLASS. 10PCS

This page is printed from:

https://www.wilhelmsen.com/product-catalogue/products/welding/arc-welding-equipment/welders-protection/shade-11-glass.-5set